

**FITNESS CERTIFICATE**  
**(ASSISTANT ENGINEER)**

1. Name of the Officer : Ramesh Kumar N (Assistant Engineer)
2. Name of the School : MOUNT FLOWER ENGLISH SCHOOL
3. Location with name of Edu Dist/Sub Dist : Thalassery,Irity
4. Classification of Building and size : 50.60X8.20X3.60 (G F), 50.60X8.20X3.60 (F F)  
3X6.10X6.10X3.62 ,1X12.56X6.02X3.62  
1X6.37X6.03X3.62 ,1X6.16X6.27X3.59  
1X6.16X6.15X3.60 ,1X6.16X6.00X3.60  
1X12.51X6.14X3.60 ,1X6.37X6.08X3.60  
2X6.27X6.09X3.60 ,2X6.11X6.08X3.60  
2X6.17X6.09X3.60 (Total 30 class rooms)
5. Period for which the certificate is issued : 2025-2026
6. Nature of defects, if any
- a. Foundation and basement : Nil
- b. Superstructure : Nil
- c. Doors and Windows : Nil
- d. Wood work wrought and put up : Nil
- e. Roof : Nil
- f. Flooring : Nil
- g. Miscellaneous (Cracks, etc.) : Nil
7. Any major defects noticed which will render the building unsafe in any manner : Nil
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Structure is sound for conducting classes  
Under normal wind and weather condition

Note :

1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Certified that the school building was inspected by me on 27-05-2025, and found to be fit to conduct classes, for the period 2025-2026 and reasons stated above.

Place : Irity  
Date : 31/05/2025



(Seal)

*R.K.S.*  
31/5/25  
ASSISTANT ENGINEER  
LID & PW SECTION  
IRITTY MUNICIPALITY  
PUNNAD P.O.